
Para Español, vea página 2.
Pour le français, consulter la page 3.

ULINE H-9550

SCOTT® PRO™ AUTOMATIC PAPER TOWEL DISPENSER

1-800-295-5510
uline.com




TROUBLESHOOTING

OPERATING ISSUE	RECOMMENDATIONS
Unit will not dispense.	Ensure cover is closed and securely latched. Replace batteries if LED indicator light is flashing. Ensure batteries are installed and oriented properly. Remove and re-install batteries.

ULINE H-9550

SCOTT® PRO™ DESPACHADOR AUTOMÁTICO DE TOALLAS DE PAPEL

800-295-5510
uline.mx




SOLUCIÓN DE PROBLEMAS

PROBLEMA DE FUNCIONAMIENTO	RECOMENDACIONES
La unidad no despacha.	Asegúrese de que la cubierta esté cerrada y bien asegurada. Cambie las baterías si la luz indicadora LED está parpadeando. Asegúrese de que las baterías estén instaladas y orientadas correctamente. Quite y vuelva a colocar las baterías.

ULINE H-9550

SCOTT[MD] PRO[MC] DISTRIBUTEUR DE SERVIETTES EN PAPIER AUTOMATIQUE

1 800 295-5510
uline.ca



DÉPANNAGE

PROBLÈME	RECOMMANDATIONS
L'appareil ne distribue pas le papier.	Vérifiez que le couvercle est fermé et bien verrouillé. Remplacez les piles si le voyant lumineux clignote. Assurez-vous que les piles sont installées et orientées correctement. Retirez et réinsérez les piles.