



INSTRUCTIONS

1. Connect cradle to host interface. (See Figure 1)




3. Battery insertion/removal. (See Figure 3)



NOTE: For best performance, fully charge the scanner battery before using the scanner for the first time.

2. Plug adapter into power source and base station. (See Figure 2)
4. Scan the appropriate barcode from original Quick Start Guide included in the box.




ULINE H-6673

ESCÁNER DE CÓDIGOS DE BARRAS


800-295-5510

uline.mx




INSTRUCCIONES


1. Conecte la base al interfaz de entrada.
(Vea Diagrama 1)



3. Inserción/Remoción de la Batería. (Vea Diagrama 3)



2. Conecte el adaptador a la fuente de alimentación y a la estación de la base. (Vea Diagrama 2)




- NOTA: Para un mejor desempeño, cargue por completo la batería del escáner antes de utilizarlo por primera vez.
4. Escanee el código de barras adecuado en la Guía de Inicio Rápida (Quick Start Guide) que se incluye en la caja.

ULINE H-6673

**SCANNER DE
CODE À BARRES**


1-800-295-5510

uline.ca




INSTRUCTIONS

1. Connectez la station d'accueil au système hôte.
(Voir Figure 1)




3. Insérer et retirer la batterie. (Voir Figure 3)



REMARQUE : Pour de meilleurs résultats,
chargez complètement la batterie du
scanner avant la toute première utilisation.

2. Branchez l'adaptateur dans une source
d'alimentation et dans la station de base.
(Voir Figure 2)



4. Scannez le code à barres approprié se trouvant sur
le Guide original de démarrage rapide fourni dans
la boîte.