



APPLICATION

Figure 1




1. Clean and dry surface where decal will be applied.
2. Slowly pull back release liner to expose adhesive back. (See Figure 1)
3. Position and apply decal to clean surface.

Figure 2




4. Apply pressure to back of decal so it adheres to surface. Slowly pull back pre-mask. Decal remains on surface. (See Figure 2)




APLICACIÓN

Diagrama 1



1. Limpie y seque la superficie donde se aplicará la calcomanía.
2. Retire lentamente el respaldo para exponer el dorso adhesivo. (Vea Diagrama 1)
3. Posicione y aplique la calcomanía para limpiar la superficie.

Diagrama 2



4. Aplique presión al dorso de la calcomanía para que se adhiera a la superficie. Retire lentamente la película de aplicación. La calcomanía permanece en la superficie. (Vea Diagrama 2)


ULINE S-23703, S-23704

S-23705

**DÉCALCOMANIE
DE RECYCLAGE**


1-800-295-5510

uline.ca



USAGE

Figure 1




1. Nettoyez et séchez la surface sur laquelle la décalcomanie sera appliquée.

2. Retirez lentement la bande antiadhésive pour exposer le côté adhésif. (Voir Figure 1)

3. Positionnez et appliquez la décalcomanie sur la surface propre.

Figure 2



4. Pressez dessus pour qu'elle adhère à la surface. Retirez lentement le ruban de prémasquage. La décalcomanie reste apposée sur la surface. (Voir Figure 2)