

ULINE H-915 INDUSTRIAL HEAT GUN

1-800-295-5510
uline.com



TROUBLESHOOTING

OPERATING ISSUE	RECOMMENDATIONS
Gun will not turn on.	If the gun has recently been used for an extended period of time, the internal thermostat may be keeping the gun from turning on. Allow the gun to cool for 20–30 minutes and try again.
Gun blows only cool air.	Adjust the dial on the back of the unit.

ULINE H-915
PISTOLA DE CALOR
INDUSTRIAL

800-295-5510
uline.mx



SOLUCIÓN DE PROBLEMAS

PROBLEMA DE FUNCIONAMIENTO	RECOMENDACIONES
La pistola no enciende.	Si acaba de usar la pistola de manera prolongada, el termostato interior puede impedir que la pistola encienda. Permita que se enfríe por 20–30 minutos e intente de nuevo.
La pistola solo emite aire frío.	Ajuste el dial posterior de la unidad.

ULINE H-915
PISTOLET THERMIQUE
INDUSTRIEL

1 800 295-5510
uline.ca



DÉPANNAGE

PROBLÈME	RECOMMANDATIONS
Le pistolet ne s'allume pas.	Si le pistolet a été utilisé récemment pendant une période prolongée, il est possible que le thermostat interne empêche le pistolet de s'allumer. Laissez le pistolet refroidir pendant 20 à 30 minutes et essayez de l'allumer à nouveau.
Le pistolet ne souffle que de l'air frais.	Réglez la molette à l'arrière de l'appareil.