Test Report

No. Date: Jan 14, 2026

Sample Description	: FABRIC FOR DRAPE
Item No.	: H-12489
Client Reference Information	: Item No.: H-12490
P.O. / Ref. No.	:
Country of Origin	: CHINA
Country of Destination	: UNITED STATES

As above test item and its relevant information regarding to the submission are provided and confirmed by the applicant. SGS is not liable to either the test item or its relevant information, in terms of the accuracy, suitability, reliability or/and integrity accordingly.

****

SGS Ref No.	:
Sample Receiving Date	: Jan 04, 2026
Test Performing Date	: Jan 04, 2026 to Jan 14, 2026
Test Performed	: Selected test(s) as requested by applicant

Test Result Summary

No.	Test(s) Requested	Result(s)	Comments
1	NFPA 701:2023 Standard Methods of Fire Tests for Flame Propagation of Textiles and Films, test method 1.	The tested sample meets the requirements of NFPA 701:2023, test method 1.	/
For further details, please refer to the following page(s)			

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Shunde Branch

Marco Leung

Marco Leung
Authorized Signatory

Scan to see the report

SDHL26010000780 1FT
Verificabcn,
check.sgsonline.com.cn

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Daliang, Shunde District, Foshan, Guangdong, China 528300 t (86-757) 22605688 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业区一号厂房首层、二层 邮编: 528300 t (86-757) 22605688 sgs.china@sgs.com

I. Test Conducted

This test was conducted in accordance with test method 1 of NFPA 701:2023 Standard Methods of Fire Tests for Flame Propagation of Textiles and Films.

II. General Information

Materials	Fabric
Area density	356 g/m^2
Products configuration	Single Layer
Size of sample *	(150 ± 5) mm × (400 ± 5) mm
Refurbishing or Weathering Conditions	NO, as per client's requirement
Conditioning	Dry at (105±3)℃, Duration: 30min

* With the length parallel to the lengthwise direction of the material.

III. Test Results

Specimen No.	Mass before test (g)	Mass after test (g)	Mass loss (%)	After flame time (s)	Burning time on floor (s)
1	21.7	18.7	13.8	0	0
2	22.3	19.3	13.5	0	0
3	23.3	19.8	15.0	0	0
4	21.8	19.1	12.4	0	0
5	21.4	18.2	15.0	0	0
6	21.5	18.0	16.3	0	0
7	22.3	18.9	15.2	0	0
8	21.9	18.9	13.7	0	0
9	21.6	18.5	14.4	0	0
10	22.0	18.6	15.5	0	0
Average	--	--	14.5	0	0
SD	--	--	1.1	--	--
3SD	--	--	3.3	--	--
AVG +/-3SD	--	--	17.8/11.2	--	--

Remark: SD – Standards deviation

IV. Conclusion:

The tested sample meets the requirements of NFPA 701:2023, test method 1.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shuxia South Road, Wusha, Dailang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805688 www.cgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处三沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805688 sgs.china@sgs.com
Member of the SGS Group (SGS SA)


Criteria for test method 1 (Chapter 10):

10.1.1.1. Fragments or residues of specimens that fall to the floor of the test chamber shall not continue flaming for more than an average of 2 seconds per specimen for the sample of 10 specimens.

10.1.1.2. The average weight loss of the 10 specimens in a sample shall be 40 percent or less.

10.1.1.3. No individual specimen's percent mass loss shall deviate more than 3 standard deviations from the mean for the 10 specimens.

Photo Appendix:



Remark: According to client's statements, the tested Style/Item No. H-12489 is identical to the Style/Item No. as stated in "Client Reference Information" column on the first page.

End of Report

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

1-2/F, Building1, European Industrial Park, No.1, Shunte South Road, Wusha, Daliang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居委会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com