


ULINE H-12760

ROBE HOOK

1-800-295-5510
uline.com




TOOLS NEEDED



Drill




1/8" Drill Bit




Phillips
Screwdriver



Allen Wrench
(included)



3/4" Apache 200 Drill Bit
(H-6486-BIT)
(optional)




Hammer
(optional)




Stud Finder
(optional)

PARTS



Flange x 1



Hook x 1




Stainless Steel
Screw x 1



Set Screw x 1



3M Waterproof
Tape x 1





H-12861 Fastener x 1
(not included)

INSTALLATION

1. Mark mounting hole location in wall with pin on end of hook. (See Figure 1)


! **IMPORTANT!** If mounting into wall studs, ensure marked locations align with wall studs.

2. Place waterproof tape on back of flange. (See Figure 2)




MOUNTING


WALL STUD MOUNTING



 **NOTE:** Do not use in ceilings. Never install any fastener into wet or deteriorating walls.

1. Drill hole using 1/8" drill bit at previously marked locations. (See Figure 3)



2. Insert included stainless steel screw into flange. Align screw with drilled hole in wall. Secure flange to wall with stainless steel screw using a Phillips screwdriver. (See Figures 4-5)


 **NOTE:** Ensure set screw hole is facing 90 degrees to the left or right.




3. Proceed to Hook Installation on page 4.

HOLLOW WALL MOUNTING


 **NOTE:** Setup is designed to accommodate wall substrates up to 1 1/8" thick.

 **NOTE:** Uline model # H-12861 fastener is recommended for this mounting method. Call Uline Customer Service at 1-800-295-5510 to order.


1. Drill hole using 3/4" Apache 200 drill bit at previously marked locations. (See Figure 6)



2. Remove one side of tape ring from H-12861 fastener kit and stick onto anchor body face plate. (See Figure 7)




3. Find flat, secure surface. Using your palm, pop winged top onto anchor body. (See Figure 8)




MOUNTING CONTINUED

4. Extend winged top to full length. (See Figure 9)





5. Compress winged top and insert anchor into wall. (See Figures 10)


 **NOTE:** Wing tips should be flush with surface when fastener is inserted into wall.



6. Gently tap anchor through wall with hammer until face plate is flush with wall surface. (See Figures 11-12)




7. Remove remaining tape ring cover on anchor face plate. (See Figure 13)




8. Align flange with anchor in wall. Insert bolt through flange and into anchor. (See Figure 14)

 **NOTE:** Ensure set screw hole is facing 90 degrees to the left or right.



9. Tighten screw with Phillips screwdriver to secure flange to wall. (See Figures 15)



10. Proceed to Hook Installation on page 4.

INSTALLATION CONTINUED

HOOK INSTALLATION

Insert hook into flange and tighten set screw with Allen wrench. (See Figure 16)

