


**ULINE** H-9550, H-9551  
**SCOTT® PRO™ AUTOMATIC  
PAPER TOWEL DISPENSER**

**1-800-295-5510**  
uline.com




## TROUBLESHOOTING

| OPERATING ISSUE         | RECOMMENDATIONS  |
|-------------------------|--|
| Unit will not dispense. | Ensure cover is closed and securely latched.<br>Replace batteries if LED indicator light is flashing.<br>Ensure batteries are installed and oriented properly.<br>Remove and re-install batteries. |

**ULINE** H-9550, H-9551

**SCOTT® PRO™ DESPACHADOR  
AUTOMÁTICO DE TOALLAS  
DE PAPEL**

**800-295-5510**  
uline.mx



**SOLUCIÓN DE PROBLEMAS**


| PROBLEMA DE<br>FUNCIONAMIENTO | RECOMENDACIONES   |
|-------------------------------|---|
| La unidad no despacha.        | Asegúrese de que la cubierta esté cerrada y bien asegurada.<br>Cambie las baterías si la luz indicadora LED está parpadeando.<br>Asegúrese de que las baterías estén instaladas y orientadas<br>correctamente. Quite y vuelva a colocar las baterías. |

**ULINE** H-9550, H-9551

**SCOTT<sup>MD</sup> PRO<sup>MC</sup>**

**DISTRIBUTEUR DE SERVIETTES  
EN PAPIER AUTOMATIQUE**

**1 800 295-5510**  
**uline.ca**



## DÉPANNAGE

| PROBLÈME                               | RECOMMANDATIONS   |
|--|---|
| L'appareil ne distribue pas le papier. | Vérifiez que le couvercle est fermé et bien verrouillé.<br>Remplacez les piles si le voyant lumineux clignote.<br>Assurez-vous que les piles sont installées et orientées correctement. Retirez et réinsérez les piles. |