


ULINE S-24344
GLASS ROLL-ON BOTTLE

1-800-295-5510
uline.com




TROUBLESHOOTING

OPERATING ISSUE	CAUSE	RECOMMENDATIONS
Not leakproof or airtight.	Roller ball not inserted securely.	Roller ball requires force when inserting by hand. Manual presses may be preferred for high volume users.
Roller ball doesn't fit into housing.	Roller ball not inserted completely.	Press firmly until three clicks are heard.

ULINE S-24344
FRASCO DE VIDRIO
ROLL-ON

800-295-5510
uline.mx




SOLUCIÓN DE PROBLEMAS

PROBLEMA DE FUNCIONAMIENTO	CAUSA	RECOMENDACIONES
No es a prueba de fugas ni hermético.	La esfera giratoria no está bien colocada.	Se requiere fuerza al insertar la esfera giratoria a mano. Se recomiendan las prensas manuales para usuarios de volúmenes grandes.
La esfera no encaja en la carcasa.	La esfera giratoria no se insertó completamente.	Presione firmemente hasta escuchar tres clics.

ULINE S-24344
FLACON EN VERRE
À BILLE

1 800 295-5510
uline.ca



DÉPANNAGE

PROBLÈME	CAUSE	RECOMMANDATIONS
La bouteille n'est ni étanche, ni hermétique.	La bille n'est pas insérée correctement.	L'insertion manuelle de la bille nécessite de la force. Les presses manuelles peuvent être préférables pour les utilisateurs de gros volumes.
La bille ne tient pas dans son emplacement sur la bouteille.	La bille n'est pas insérée complètement.	Appuyez fermement jusqu'à entendre trois déclics.