



## TAPE GUIDE

### WHICH TAPE SHOULD I USE?

FEATURE	Uline Industrial	Uline Economy	Uline Natural Rubber – Polypropylene	Uline Natural Rubber – PVC
Adhesion to Corrugated	Excellent	Good	Excellent	Excellent
Application Temperature Range	-18° – 60°C (0° – 140°F)	10° – 43°C (50° – 110°F)	-18° – 66°C (0° – 150°F)	-18° – 66°C (0° – 150°F)
Performance Temperature Range	-51° – 60°C (-60° – 140°F)	-1° – 60°C (30° – 140°F)	-30° – 129°C (-22° – 265°F)	-20° – 71°C (-4° – 160°F)
Clarity	Excellent	Good	Good	Good
Moisture Resistance	Very Good	Fair	Very Good	Very Good


### WHICH MIL SHOULD I USE?

CARTON WEIGHT	65-90 LBS.					3.5 MIL
	50-65 LBS.				3.0 MIL	
	35-50 LBS.			2.5-2.6 MIL		
	15-35 LBS.		2.0 MIL			
	0-15 LBS.	1.7-1.8 MIL				
	0"	20"	40"	60"	80"	100"
BOX LENGTH + WIDTH + HEIGHT						

### HELPFUL HINTS

- Always seal boxes with one strip of tape.
- If you are using 2 strips of 2" tape, try a 3" tape or a thicker mil. This will save time and money.

2"	• For boxes 15" wide or less.
3"	• Boxes over 16" wide. • Underfilled RSC boxes. • Overstuffed boxes. • Difficult to adhere surfaces.



1-800-295-5510 [uline.ca](http://uline.ca)